

PORT OF GREAT YARMOUTH

NOTICE TO MARINERS

No. 4 of 2011

Outer Harbour Entrance Obstruction

NOTICE IS HEREBY GIVEN that an obstruction exists in the south side of the Outer Harbour entrance, 30 metres north of the Qk Fl red light (52° 34.6N, 01° 44.73E) that is exhibited at the end of the south breakwater. Steel structures above and below the waterline in this locality present a danger to navigation. The area is marked just to the east by a red can buoy in approximate position 52° 34.615N, 01° 44.75E exhibiting a red light group flash 2 every 5 seconds FI(2)R5s

Mariners are advised to avoid the area and not pass closer than 50 metres from the Qk Fl Red light mentioned above.

Captain P. J. McNamara
Harbour Master
(Great Yarmouth Port Company Ltd
as Agent for Great Yarmouth Port Authority)